# Installation Instructions for Shielding






1. Remove the screws in the PE bag and fix the hood to the light fixture along the dotted line.

Technical requirements:
1.Material: Galvanized sheet

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| WSD LED INC Green Lighting Resources | | | edition | Modifier | Time of modification | Repair the interior | |
| Material No. | 317.0036 | Edition | A/0 | Page 1/1 | Tolerance requirements:(tolerance without special requirements) | | Date |
| Material Name | WSD-AL-150W-HOOD-D | proportion | | Angle | NO ± 0.2 | mapping | |
| Specification Description | | unit | | | .x ± 0.1 | check | |
| Drawing Number | | material quality | | | .xx ± 0.05 .xxx± 0.015 | examine and verify | |