

Installation guide



1.Fix the surface mount bracket with screws(Note that the distance between the two suface mount brackets is within the specified range).



2.Install che fixture to the mount suface with screws.